



December 15, 2016

Preliminary Metallurgical Results Received for the Boleras Main Zone at the Sandra Escobar Project in Durango, Mexico

Vancouver, BC – Orex Minerals Inc. – (TSX-V: REX) (“Orex”), has received preliminary metallurgical test results for samples from the Main Zone of the Boleras Silver Deposit at the Sandra Escobar Project in Durango, Mexico. This project is being advanced by Orex under an option agreement with **Canasil Resources Inc. – (TSX.V: CLZ)** (“Canasil”).

Results are now available for five samples, with increasing head grades, taken from across the Main Zone of the Boleras Silver Deposit. These results illustrate that recovery is grade dependent. A portion of the silver-bearing mineralogy is recoverable with leaching techniques, including hydrochloric acid (HCl), or sulphur dioxide (SO₂) pre-treatment before cyanidation, and a portion is refractory, requiring more investigation. An extra high-grade sixth sample was also prepared for mineralogical work and was tested by the same methods at the Kemetco Research Inc. (“KR”) laboratory.

Initial interpretation of the results suggests that there are three different hosts of silver; 1) a small amount of direct cyanide leachable silver (native silver and silver halides, cerargyrite and bromargyrite), 2) a varying amount of silver-bearing minerals leachable under pre-treatment conditions (argentiferous manganese and iron oxides, pyrolusite and aurorite), and a portion within silicate minerals.

Table 1. – Boleras Main Zone – Metallurgy – HCl Pre-treatment

Preliminary HCl Leach Results		
Sample	Head Grade - Ag (g/t)	Recovery – Ag (%) – KR
1 #SE	54	6.1
2 #SE	98	14.5
3 #SE	143	26.8
4 #SE	192	29.4
5 #SE	361	63.3
6 #SE	1812	93.0





Table 2. – Boleras Main Zone – Metallurgy – SO₂ Reduction Pre-treatment

Preliminary SO ₂ Leach Results		
Sample	Head Grade - Ag (g/t)	Recovery – Ag (%) – KR
1 #SE	54	4.6
2 #SE	98	8.1
3 #SE	143	22.7
4 #SE	192	24.5
5 #SE	361	58.7
6 #SE	1812	83.0



Geological comparisons have been drawn between the mineralization styles at Sandra Escobar and the La Pitarrilla project of Silver Standard Resources Inc., located 75 km to the east. At La Pitarrilla, the Cordon Deposit is also an iron and manganese oxide hosted silver resource, within a rhyolite host rock unit, and is part of a much larger volcanoclastic complex. Structural and stratigraphic controls to mineralization are present in both locations. The Cordon Deposit has been shown to be a peripheral deposit to a much larger sulphide silver and base metals resource at depth. The Boleras deposit at Sandra Escobar is geologically similar to the Cordon deposit at La Pitarrilla and may be analogous in forming part of a larger mineralized system.

Orex's President, Gary Cope says, *"While the preliminary metallurgical results are not ideal for the Boleras Main Zone, the comparisons between Sandra Escobar geology and that of the neighbouring La Pitarrilla project are encouraging."*

Guidance for the metallurgical test work has benefited by the consulting services of Blue Coast Metallurgy of Parksville, BC, Canada.

Sandra Escobar Silver-Gold Project, Durango, Mexico

Sandra Escobar is situated north of the town of Tepehuanes, Durango, in the heart of the "Mexican Silver Trend", midway between the mining districts of Tovar and Guanacevi and is 75 km west of Silver Standard's La Pitarrilla. This prolific trend hosts some of the world's largest silver camps and deposits, including Fresnillo, Guanajuato, La Pitarrilla, La Preciosa, Real de Angeles and Zacatecas.

The project consists of 6,333 hectares of mineral concessions and covers multiple mineralized epithermal quartz veins and breccia structures. These veins form a high level silver-gold-base metals system, hosted in andesitic and rhyolitic rocks, centered on a large rhyolite dome complex in the north and silver systems in smaller rhyolite dome complexes to the southeast. All within a large caldera complex. Intense alteration zones and fluid flooding in permeable formations indicates the presence of bulk tonnage targets. Excellent infrastructure exists in the Sandra Escobar area, including paved road access, electrical power, water and manpower from nearby communities.

Orex has drilled 8,372 metres in 62 diamond drill holes in the southeastern region of the project. The first 59 diamond drill holes formed the basis for an initial Resource Estimate on the "Boleras Silver Deposit." At a "Base Case" of 45 g/t Ag cut-off, the **Inferred Resource Estimate yielded 9.8 million tonnes grading 106 g/t Ag for a total of 33.3 million ounces of silver** (See Orex news release of 31 October 2016). This Inferred Resource Estimate can be sub-divided into a high-grade domain of 0.7 million tonnes grading 288.4 g/t Ag, representing approximately 20% of the contained silver, plus an average-grade domain of 9.1 million tonnes grading 91.7 g/t Ag, representing approximately 80% of the contained silver.

Note: Mineral Resources are not Mineral Reserves and do not have demonstrated economic viability. There is no certainty that all or any part of the estimated Mineral Resources will be converted into Mineral Reserves. The estimate of Mineral Resources may be materially affected by environmental, permitting, legal, title, taxation, sociopolitical, marketing, or other relevant issues.

The technical disclosures contained in this news release have been approved by Ben Whiting, P.Geo., and Dale Brittliffe, P.Geo., both being "Qualified Persons" as defined in NI 43-101 on behalf of Orex.

ABOUT OREX MINERALS INC.

Orex is a Canadian-based junior exploration company comprised of highly qualified mining professionals. Orex has several current projects: the Coneto Gold-Silver Project in Durango, Mexico, a joint venture with Fresnillo PLC, the Sandra Escobar Silver Project in Durango, Mexico, a joint venture with Canasil Resources Inc., plus the Jumping Josephine Gold-Silver Project in British Columbia, Canada.

ON BEHALF OF THE BOARD OF DIRECTORS

Gary Cope
President

For further information, please contact **Orex Minerals Inc.** at (604) 687-8566 x227, email info@orexminerals.com or visit our website at www.orexminerals.com

Certain statements in this news release constitute "forward-looking statements" or "forward-looking information" with the meaning of applicable securities laws, including but not limited to comments regarding the timing and content of upcoming work programs, geological interpretations, receipt of property titles, and potential mineral recovery processes.

Such statements involve known and unknown risks, uncertainties and other factors which may cause the actual results, performance or achievements of Orex, or industry results, to be materially different from any future results, performance or achievements expressed or implied by such forward-looking statements or forward-looking information. Such statements can be identified by the use of words such as "may", "would", "could", "will", "intend", "expect", "believe", "plan", "anticipate", "estimate", "scheduled", "forecast", "predict" and other similar terminology. These statements reflect Orex's current expectations regarding future events, performance and results and speak only as of the date of this news release and Orex undertakes no obligation to update such statements, except as required by law.

All such forward-looking statements and information are based on certain assumptions and analyses made by Orex's management in light of their experience and perception of historical trends, current conditions and expected future developments, as well as other factors management believes are appropriate in the circumstances. These statements, however, are subject to a variety of risks and uncertainties and other factors that could cause actual events or results to differ materially from those projected in the forward-looking statements or information, including, but not limited to unexpected changes in laws, rules or regulations, or their enforcement; the failure of parties to contracts to perform as agreed; social or labor unrest; changes in commodity prices; unexpected failure or inadequacy of infrastructure and the failure of exploration programs or other studies to deliver anticipated results or results that would justify and support continued studies, development or operations. Readers are cautioned not to place undue reliance on forward-looking statements or information.

Neither TSX Venture Exchange nor its Regulation Services Provider (as that term is defined in the policies of the TSX Venture Exchange) accepts responsibility for the adequacy or accuracy of this news release.